



La Linea “Face”

Drilling table

- ① Drill the holes at the coordinates indicated in the table on page 2 by the X and Y values.
- ② The fixing holes are listed and indicated in page 1 by this symbol: 
- ③ Install the product starting from number 1.



N° Holes	X	Y
1	3314	0
2	3128	559
3	2810	1120
4	2461	1352
5	1923	1358
6	1356	1241
7	824	1412
8	806	1694
9	702	1921
10	714	2157
11	913	2296
12	931	2179
13	693	2251
14	580	2556
15	585	2777
16	453	2974
17	636	2870
18	437	2838
19	291	2926
20	281	3110
21	507	3460
22	743	3870

N° Holes	X	Y
23	730	4141
24	708	4654
25	857	5076
26	1026	5429
27	590	5614
28	133	5131
29	0	4689
30	263	4182
31	1075	3846
32	1751	3591
33	2137	3228
34	1728	2508
35	1469	1855
36	1760	1527
37	2283	1563
38	2800	1691
39	3172	1375
40	3277	983
41	3684	869
42	4172	992
43	4165	1406